This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.







FIG.3



SEACON LSG-6-BC-1P bulk head connector

SEACON RMG-6-FS inline Connector (waterblocked)

Waterblocked breakout splice (Scripps)

Length of Nylon tube breakout to be 0.5 in, longer than the length of the RMG breakout. Use the face of the RMG connector and the furthest extent of the shortest Nylon tube as admining points.


Length of breakout splice to be as short as possible

Custom Heater element with through conductor and ground conductor.

Heater Cartridge Insert

Modified probe

O-ring sealed gas passages 4 # 10 Cap Screws perpendicular to probe surface equally spaced



Detail A

FIG. 4B

- 0.060 x 45 degree chanfer
 Parker Hannifin Corporation O-ring groove
 Broach 0.0625 wide groove as shown
 Material-cold rolled stee!
 Hold these dianneters concentric within 0.003 in.
 Hold all concentric diameters within 0.025 in. unless noted otherwise




FIG. 4C

Match sample thread form
Smalley WH-150 snap ring
Matchial-cold rolled steel
Break all edges to 0.030 R min.
Hold these diameters concentric within 0.003 in.
Hold all concentric diameters within 0.025 in. unless noted otherwise






FIG. 40

Detail B











FIG. 7

TRUNK
LINE
(CARRIER
GAS)
808

FIG. 9B







PROCESSING

· Quality Assurance/ Quality Control -

Error trapping

Data normalization

Variations

 Actual Subsurface Condition Condition of Membrane

·Chemical Concentration Soil/Water Matrix

Pressure

·Flow Rate

-Condition of Detectors -

. Drift

·Calibration Depth of Probe

Baseline Noise Analytical/Electrical System ·Hydrostatic

Aggregation

 Predictive measure of Risk/Performance Site and contaminant comparison


Formatting and visualization

- 13.4E * * *

The state of the s

fmeyer EGD.Blane, B-ES EGD.plum, 5-EE

FIG. 12A



DemoCorp

Demo Corp

SmartData Solutions"

Featured Projects

SmartData Solutions was used to delineate a source area under a manufacturing building. The resulting 3D images helped to focus remedial efforts, thereby saving time and cost. Earth Tech's client remarked, "This was the best data he had ever seen!" Dave Rosecrance of Oak Ridge, Tennessee was asked by the TDEC to present the results at their Haz Waste conference in Gatlinburg, Tennessee in May 2002.

Welcome back John Smith

(Not John Smith? Click here

Your Current Projects

PETROLEUM TERMINAL

MANUFACTURING FACILITY

Other Demo Corp Projects

Brownfield Site

Irving Lambert - San Francisco

Dry Cleaner

Anna Cohen - Tampa

Gas Station

Vernon Wilkes - Baltimore

Vapor Intrusion Site

Sam Fisher - Dallas

Assistance

Customer services
We strive to provide all our customers with the best service possible. If you are experiencing a problem, please do not nesitate to call our customer service department toll-free on 1-888-344-2704

Contact Legal Privacy

FIG. 12C

DemoCorp

Your Protects

Manufacturing Facility





SmartData Solutions**

Site Information

Manufacturing Facility Savanna, GA **Project Dates**

Started:

8/12/2002

Completed:

8/21/2002 Status

Completed

Movie Information

Play the movie

The Movies (AVI files) contained on this CD can be viewed with Nicrosoft Hedia Player. In the event the movie does not play, you may need the appropriate decompression software.

We have enclosed this software on the CD. To install this software. simply run the file and select "install" when prompted

> Install Decompression Software

Click the link above, then click "Open" to run setup program.

D Use another Media Player then what comes with Windows As an alternative to Media Player, we have included a viewer called Camtasia Player that can be installed free of charge. This is in our view a very good product and should he used in case Hedia Player fails to play the

□ Completed Deliverables

As your order is completed, each item will be added to this screen. Your sitemap is still available by clicking on the "Sitemap" heading below.

You can get this content delivered to you on a CDROM, please contact your sales representative or the <u>SmartData Solutions</u> <u>Team</u> for assistance.

■ Sitemap

Images

ECD 1+E6, Plan View (Full site)	[71 kp
ECD 1+E6, Plan View	71 Fb*
ECD 5+E6, Plan View	Foo kb
ECD 5+E5, Transect	[71 kb
ECD Slice, Lab Data	[81 kb]

D Movies

ല് Plan View,	360 Fly-around (Lab Data)	[11 mb]
@ Plan View,	360 Fly-around (Full site)	(41 mb

■ Presentations

Smart Data	Solutions ***	Overview
------------	---------------	----------

,2 mb;

Webcast

View



MIP Logs

CRT01CPC FGCFT02 FGCFT02 FGCFT03 FGCFT04 PGCFT06 PGCFT06 PGCFT07 PGCFT08 FGCFT09 PGCFT12 FGCFT15 FGCFT15 FGCFT15 FGCFT16 FGCFT16 FGCFT16 FGCFT16 FGCFT16 FGCFT16 FGCFT16

Assistance

We strive to provide all our customers with the best service possible. If you are experiencing a problem, please do not hesitate to call our customer service department toll-free on 1-888-344-2704

FIG. 12D

FIG. 12E